BETHEL PARK ELEMENTARY CENTER

CONSTRUCTION UPDATE

10-14-2025









• Bus Loop grading for paving











• E wing Northside long board and flashing complete











Long board wrapping around into courtyard







• Flashing installed on F wing followed after completion of window frames







Ground floor E hallway painting







Ground floor E classrooms casework and ceiling grid
 (only needing floors and ceiling tile to complete)






Ground floor F half of wing painted waiting for casework





Other half of F wing drywall and finishing





Ground floor A, C, and D hallway drywalled working on finishing





Completely roofed in







THANK YOU



Project Stats

 Safety = 440 Days with Zero Recordable Accidents

Upcoming Work

- Drywall and finishing 1st flr
- Finishing and painting ground flr
- Installing casework in ground flr E
- Installing a road around building
- Installing RTU's